



Dewatered pond facing upstream with stream channel beginning to establish (April 2015).



Construction of access road in dewatered pond to prepare for culvert boring with old spillway in foreground (April 2015).





Natural vegetation establishment in dewatered pond (July 2015).



Vegetation establishment after native seed and cover crop seed applied (August 2015).





Vegetation establishment after native seed and cover crop seed applied (August 2015).



Boring pit for new culvert downstream of dewatered pond (August 2015).





Close-up of culvert boring downstream of dewatered pond (August 2015).



New culvert and headwall downstream of dewatered pond, facing southwest toward Morley Road (October 2015).





Dewatered pond with naturally established stream entering new culvert (October 2015).



Construction crew working on temporary access road to reach upstream-most section of the restoration area (March 2016).





Newly installed log sill on the north bank of the stream to the left and the start of the cascade inlet structure to the new culvert on the right (March 2016).



Newly installed cascade inlet structure to the new culvert on the right (March 2016).





Cascade inlet structure to the new culvert on the right (June 2016).




Log sill on the north and south bank of stream in center and start of riffle on the right (June 2016).





Upstream view of postings and riffle (June 2016).



Upstream view of project area from Morley Road (June 2016),



Project sign adjacent to restoration area.





Project sign along Morley Road.